

# Workpackage-Summary

 P120218  
 06:07

 22.May.2018  
 Page 1/5

## Workpackage XLH/HM-10.2018 AD for EI-XLH, the 05.Nov.2018 (19:48) in VKO

A/C-Type: B747, SerialNo: 27650, Manufacture-Date: 20.11.1999, Delivery-Date: 12.10.2016, Expire-Date: 11.10.2023

Based on last Flight Log entry from Friday 18 May 2018 ; TAH: 57084:12 ; TAC: 7'840

Description: AD



WP163847

No.	W/O	ATA	W/O or Maintenance Event Description	Est.MH	To Go	Prio	T	H	M	Pickslip	Performed/Comments
1	502506804	21-44	ZONE TEMPERATURE SENSOR INSTALLATION FAA AD 2015-11-05 21 MAY 2015	73:30/?	776/D	1 P108964	SD			Not issued	
2	502591985	34-00	AIR DATA SYSTEM - ALTIMETRY SYSTEM TEST SB 747-34-3020 REVISION 2: JUNE 19, 2015	06:30/?		1 P108932	SD			Not issued	
3	504590730	31-31	MANDATORY: PERFORM EOD EOD-747-31-31-001 (ENGINEERING ORDER DETAIL) REV. 00	00:00/?		1 P108932	SD				
4	504081722	51	STEP 1 PERFORM REPLACEMENT OF ALL TECHNICAL MARKINGS ON THE WING LOWER	12:00/?	613/D	3 P108931	SD			Not issued	
5	504144139	25-21-45	PASSENGER COMPARTMENT CROWN INSULATION BLANKET INSPECTION ZONE C DO THE PASSENGER COMPARTMENT CROWN INSULATION	06:00/?	527/D	3 P108932	SD				
6	504344283	25-21-45	PASSENGER COMPARTMENT CROWN INSULATION BLANKET INSPECTION ZONE E DO THE PASSENGER COMPARTMENT CROWN INSULATION	08:00/?	557/D	3 P108932	SD				
7	504344284	25-21-45	PASSENGER COMPARTMENT CROWN INSULATION BLANKET INSPECTION UPPER DECK DO THE PASSENGER COMPARTMENT CROWN INSULATION	08:00/?	557/D	3 P108932	SD				
8	504410085	57-53	COVE LIP DOOR INSPECTION PLEASE PROVIDE OUTBOARD MID FLAP COVE LIP DOOR INSPECTION. CHECK	05:00/?	140/D	3 P108932	SD				
9	504429918	25-21-45	PASSENGER COMPARTMENT CROWN INSULATION BLANKET INSPECTION ZONE D DO THE PASSENGER COMPARTMENT CROWN INSULATION	06:00/?	619/D	3 P108932	SD				
10	504429919	25-21-45	PASSENGER COMPARTMENT CROWN INSULATION BLANKET INSPECTION ZONE A DO THE PASSENGER COMPARTMENT CROWN INSULATION	06:00/?	619/D	3 P108932	SD				

# Workpackage-Summary

 P120218  
 06:07

 22.May.2018  
 Page 2/5

No.	W/O	ATA	W/O or Maintenance Event Description	Est.MH	To Go	Prio	T	H	M	Pickslip	Performed/Comments
11	504431024	74	PERF. TASKCARD 747-11-0001, REV. 00 EXTERNAL MAINTENANCE MARKING INSTALLATION INSPECTION IAW ATTACHED JOB	06:00/?	172/D	3 P108931	SD				
12	504431038	51	PERF. TASKCARD 51-03-001-SDM, REV. 00 AIRCRAFT STRUCTURE DAMAGE EVALUATION	12:00/?	172/D	3 P108931	SD				
13	504431043	51-21	INSPECTION AND REPAIR OF EXTERIOR PAINTED SURFACES ON AIRCRAFT PERFORM A/C VISUAL INSPECTION OF ALL PAINTED SURFACES FOR DAMAGES. IN	04:00/?	172/D	3 P108931	SD			Not issued	
14	503267842	51-20	DECORATIVE FINISHING OF AIRPLANE EXTERIOR INSPECTION JIC SHOULD BE STARTED AT EARLY STAGE OF THE MAINTENANCE PERIOD	01:00/?	141/D	4 P108964	SD			Not issued	
15	503866180	51-31-00	AERODYNAMIC SEALS - INSPECTION FOR ALLOWABLE DAMAGE LIMITS PERFORM AN INSPECTION OF THE AERODYNAMIC SEALS	12:00/?	499/D	4 P108932	SD				
16	504440510	21-00	AIR DISTRIBUTION SYSTEM MAINTENANCE DO THE AIR DISTRIBUTION SYSTEM INSPECTION IAW ATTACHED JOB INSTRUCTION	50:00/?		4 P108931	SD			Not issued	
17	502459120	57-15-00	PART 7 - SB 747-57A2331 R01 FOR GROUP 6 AIRPLANES PERFORM LH WING LANDING GEAR (WLG) SUPPORT BEAM END FITTINGS REPAIR OR	60:00/?	204/D	AD P108964	SD			Not issued	
18	502459245	57-15-00	PART 7 - SB 747-57A2331 R01 FOR GROUP 6 AIRPLANES PERFORM RH WING LANDING GEAR (WLG) SUPPORT BEAM END FITTINGS REPAIR OR	60:00/?	204/D	AD P108964	SD			Not issued	
19	502478038	53-12	INSPECTIONS FOR BROKEN FASTENERS AT FWD EDGE FRAME OF MED 3 (GROUP 7) FAA AD 2000-02-10 REV.00	03:00/?	2'160/C	AD P108964	SD			Not issued	
20	502478774	53-00	SKIN CRACKS AT THE DRAG SPLICE FITTING AT STR. 38, BS 980 (GR.1 OF SB) FAA AD 2001-22-04 REV.00	11:40/?	2'160/C	AD P108964	SD				
21	502479514	54-10	BASELINE INSPECTION - GROUP 6 OF SB. FAA AD 2005-03-01 REV.00, PARA. (B)- BASELINE INSPECTION.	36:00/?	868/D	AD P108964	SD			Not issued	
22	502479907	53-10	INSPECTIONS OF THE BULKHEAD CHORD & BATHTUB FITTINGS - GROUP 7 OF SB. FAA AD 2005-10-21 REV.00, PARA. (H).	38:00/?	2'160/C	AD P108964	SD			Not issued	

# Workpackage-Summary

 P120218  
 06:07

 22.May.2018  
 Page 3/5

No.	W/O	ATA	W/O or Maintenance Event Description	Est.MH	To Go	Prio	T	H	M	Pickslip	Performed/Comments
23	502479977	53	AD 2006-06-10 - INSPECTION OF INSTALLED DOUBLER TYPE AD 2006-06-10 REV.00	02:10/?	2'160/C	AD P108964					
24	502480105	27	AD 2006-10-02 TRIM DRIVE MECHANISM FREEPLAY INSPECTION PLEASE PERFORM STABILISER TRIM DRIVE MECHANISM FREEPLAY INSPECTION IAW	05:00/?	8038:48/H	AD P108964				Not issued	
25	502481632	57-52	AD 2008-25-07 - SB PART 1 - FLAP TRACK FORWARD ATTACHMENT INSPECTION PLEASE INSPECT FLAP TRACK FORWARD ATTACHMENT IAW ATTACHED JOB	20:00/?	594/C	AD P108931				Not issued	
26	502481922	53-13	FUS. STA 2403.6 TO 2524.4 UPPER LOBE DOUBLER - INSP., GROUP 2 OF SB FAA AD 2009-09-08 REV.00	25:10/?	2'160/C	AD P108964				Not issued	
27	502485143	53	OPEN-HOLE HFEC INSPECTION OF THE STA 2598 BULKHEAD FRAME SUPPORT. FAA AD 201014-07 REV.00	41:10/?	2'160/C	AD P108964				Not issued	
28	502485158	53-13	BS 2598 BULKHEAD INNER CHORD, OUTER CHORD, & DIAGONAL BRACE INSPECTION AD 2010-14-07 REV.00	20:10/?	2'160/C	AD P108964					
29	502485295	53-13	B747 AD 2014-14-03 LOWER AREA- SURFACE AND OPEN HOLE INSPECTIONS PLEASE PERFORM INSPECTION OF LOWER AREA SURFACE AND OPEN HOLE IAW	25:45/?	1'634/C	AD P108964					
30	502487079	53-13	AD 2014-14-03 PARA I(1)+I(2) - POST INTERIM MODIFICATION INSPECTION PLEASE PERFORM INTERIM MODIFICATION INSPECTION IAW ATTACHED JOB	07:30/?	753/C	AD P108931					
31	502487324	28-22	ENGINE FUEL FEED SYSTEM O/B MAIN TANK BOOST PUMP WIRING INSPECTION FAA AD 2011-15-03 REV.00	08:00/?	3029:48/H	AD P108964				Not issued	
32	502504172	53-31	INSPECTION AT THE AFT UPPER CORNER OF THE CUTOUT FOR LEFT MAIN ENTRY FAA AD 2013-19-15 REV.00	00:30/?	2'160/C	AD P108964					
33	502504175	53-31	INSPECTION AT THE AFT UPPER CORNER OF THE CUTOUT FOR RIGHT MAIN ENTRY FAA AD 2013-19-15 REV.00	00:30/?	2'160/C	AD P108964					

# Workpackage-Summary

 P120218  
 06:07

 22.May.2018  
 Page 4/5

No.	W/O	ATA	W/O or Maintenance Event Description	Est.MH	To Go	Prio	T	H	M	Pickslip	Performed/Comments
34	502509141	53-12	SURFACE HFEC INSPECTIONS OF THE RIGHT LONGERON EXTENSION FITTING. FAA AD 2015-13-06 REV.00	16:10/?	1'353/C	AD P108964					
35	502510563	53-12	SURFACE HFEC INSPECTION OF THE FRAME INNER CHORDS (LH SIDE) DO A SURFACE HFEC INSPECTION ON THE STATION 2231 FRAME INNER CHORD	02:00/?	2'160/C	AD P108964					
36	502510585	53-12	SURFACE HFEC INSPECTION OF THE FRAME INNER CHORDS (RH SIDE) DO A SURFACE HFEC INSPECTION ON THE STATION 2231 FRAME INNER CHORD	02:00/?	2'160/C	AD P108964					
37	502512562	53-10	AD 2016-05-12 PARA (J,L) - INSPECTION AND REPAIR (STAGE 2) DO THE STRETCHED UPPER DECK FRAME AND TENSION TIE INSPECTION AND	112:06/?	2'160/C	AD P108964				Not issued	
38	502512579	53-10	AD 2016-05-12 PARA (M) - INSPECTION FOR INCORRECTLY INSTALLED ANGLES DO THE ONE-TIME INSPECTION FOR MISLOCATED ANGLES IAW ATTACHED JOB	26:06/?	2'160/C	AD P108964					
39	502515885	53-11	AD 2016-06-07 PARA G(1) - DETAILED INSPECTION PERFORME EXTERNAL DETAILED INSPECTION OF THE SIDEWALL PANEL WEB AT WL	45:00/?	2'160/C	AD P108964				Not issued	
40	502625281	25-00	BMS 8-39 URETHANE FOAM REPLACEMENT DO THE FLIGHT COMPARTMENT AND CARGO COMPARTMENT - BMS 8-39 URETHANE	431:30/?	413/D	AD P108964				Not issued	
41	502649191	22-10	747 ON GROUND STABILIZER AUTOTRIM INHIBIT RELAY SYSTEM - INSTALLATION FAA AD 2016-25-01 REV.00	104:00/?	254/D	AD P108964				Not issued	
42	502680370	54-10-00	AD 2005-03-01 - SPRING BEAM OVERHAUL PLEASE PERFORM INSPECTION IN ACCORDING WITH ATTACHED JOB INSTUCTION	112:00/?	3'160/C	AD P108964				Not issued	
43	502681201	53-10	MAIN ENTRY DOOR 3 FORWARD EDGE DOOR FRAME STOP SUPPORT FITTINGS DO THE DETAILED VISUAL INSPECTIONS OF MAIN ENTRY DOOR 3 FORWARD EDGE	11:00/?	1'253/C	AD P108964					
44	502991173	53-31	SKIN INNER SURFACE INSPECTION PLEASE PERFORM SKIN INNER SURFACE INSPECTION IAW ATTACHED JOB	815:00/?	299/D	AD P108964				Not issued	

PROPERTY OF "ROSSIYA AIRLINES" JSC

SIGN/STAMP